

Message

From: Stan Carey [scarey@massapequawater.com]
Sent: 3/4/2015 2:01:10 PM
To: Fly, Lora B CIV NAVFAC MIDLANT, IPTNE [lora.fly@navy.mil]
CC: Harrington, Jim (DEC) [jim.harrington@dec.ny.gov]; Scharf, Steven (DEC) [steven.scharf@dec.ny.gov]; Paul Granger [pgranger@h2m.com]; Garbarini, Doug [Garbarini.Doug@epa.gov]
Subject: Damaged Monitoring Well

Ms. Fly,

I would just like to confirm our conversation from yesterday with regard to VPB 147 (monitoring wells 6-5 & 6-6). You advised that they were damaged during construction and can no longer be used. A new location will need to be approved and the process could take an extended period of time.

While MWD understands these issues do occur from time to time in the construction business, we are very concerned with any delays to find a new location and construct a new monitoring well. As you are aware this location had a concentration of .45 ppb TCE and potentially may be the leading edge of the plume or a southern finger. This location was specifically located and approved by MWD to provide an early warning for our Northwest wellfield.

MWD requests that the new location and well development be expedited. We would appreciate a new schedule and to be part of the new location selection process. We also offer our assistance in obtaining approvals from any agency or Town in Nassau County. Our request to collect split samples once constructed is still requested. Thank you.

Stan Carey, Superintendent
Massapequa Water District

